Royal McBee Service Bulletin...

January 25, 1963
Service Bulletin No. T-14 & D-18

ROYFAX 100 PHOTOCOPIER

PRESSURE PAD LEVER KNOB, #3-28-3

Effective immediately, all Royfax 100 Photocopiers will be shipped with the Pressure Pad Lever Knob taped to the Pressure Pad Lever to prevent damage.

Upon receipt of a Royfax 100 unit, remove the tape and thread the Knob to the Lever.

Replacement Knobs can be obtained through regular part order procedure.

CUSTOMER SERVICE PLANNING -

Per/PSC
ECN #8

TECHNICAL SERVICE PUBLICATIONS DEPARTMENT

Distribution: 5X, 5Y (Divisional Service Managers) 6X, 6Y (District Service Managers) 7, 8